

TREE #	STATION POINT	CHANGE IN GRADE	STREET	SIDE	COMMON	DIAMETER BREAST HEIGHT	CONDITION	HARDSCAPE DAMAGE	DAMAGE EXTENT (INCHES)	NOTES	MITIGATION #
1	11+72	0.49	Ebbitts St (On Milton Ave)	North	Zelkova	6	Good	No	0		STP
2	14+12	DEAD	Milton Ave	North	Zelkova	4	Dead	No	0		REMOVAL
3	14+91	1.55	Milton Ave	North	London Planetree	36	Good	No	0		REMOVAL
4	17+30	-0.01	Milton Ave	North	Sycamore Maple	20	Poor	No	0		REMOVAL
5	17+48	0.01	Milton Ave	North	Ash	8	Good	No	0	Trunk wounds	REMOVAL
6	18+11	-0.23	Milton Ave	North	London Planetree	24	Good	Yes	0	Sidewalk heaved/cracked	REMOVAL
7	18+29	-0.24	Milton Ave	North	London Planetree	26	Good	Yes	0	Sidewalk heaved/cracked	REMOVAL
8	20+31	0.41	Milton Ave	North	London Planetree	24	Good	Yes	0	Sidewalk heaved/cracked, roots girdling	REMOVAL
9	21+12	0.36	Milton Ave	North	London Planetree	36	Good	No	0		REMOVAL
10	21+49	0.23	Milton Ave	North	London Planetree	24	Good	No	0		REMOVAL
11	21+64	0.26	Milton Ave	North	London Planetree	24	Good	No	0		REMOVAL
11A	21+85	0.30	Milton Ave	North	London Planetree	24	Good	No	3	Hangers	*REMOVAL
12	22+10	0.52	Milton Ave	North	London Planetree	36	Good	No	3	Trunk decay, sidewalk heaved	REMOVAL
13	22+30	0.46	Milton Ave	North	London Planetree	28	Good	Yes	0	Sidewalk heaved	REMOVAL
	22+70	0.35			London Planetree	36	Good	No	0	Sidewaik fleaved	REMOVAL
14		0.30	Milton Ave	North				No			
15	22+90		Milton Ave	North	London Planetree	24	Good		0	Trunk would	REMOVAL
16	23+10	0.23	Milton Ave	North	London Planetree	38	Good	No	3	Trunk wounds	REMOVAL
17	23+34	0.13	Milton Ave	North	London Planetree	38	Good	No	0	Wood planter  True at a real science like to a real science in the	REMOVAL
18	23+87	-0.12	Milton Ave	North	Silver Maple	8/8	Good	Yes	1	Two stems, sidewalk heaved/cracked, roots girdling	REMOVAL
19	24+03	-0.19	Milton Ave	North	Silver Maple	17/23/11	Fair	Yes	0	Four stems, sidewalk heaved, roots girdling	REMOVAL
20	25+66	NF	Milton Ave	North			Not Found	No	0		
21	25+90	-0.66	Milton Ave	North	Oak	2	Fair	No	0	Newly planted	TRANSPLANT
22	26+12	DEAD	Milton Ave	North	DEAD	2	Dead	No	0	Newly planted	REMOVAL
23	26+34	-0.13	Milton Ave	North	London Planetree	23	Fair	No	0		REMOVAL
24	26+68	0.39	Milton Ave	North	Callery Pear	6	Good	No	3	Brick planter	REMOVAL
25	26+92	0.58	Milton Ave	North	Callery Pear	4	Good	No	3	Brick planter	TRANSPLANT
26	27+35	1.34	Milton Ave	North	London Planetree	30	Poor	Yes	0	Asphalt cracked	*REMOVAL
26A	27+64±	1.64	Milton Ave	North	London Planetree	26	Fair	Yes	1	Growing into sidewalk	REMOVAL
27	27+94	1.92	Milton Ave	North	London Planetree	25	Fair	No	0	Hangers, slime flux	REMOVAL
28	28+20	1.92	Milton Ave	North	London Planetree	24	Good	No	0		REMOVAL
29	28+51	2.30	Milton Ave	North	London Planetree	36	Fair	No	0		REMOVAL
30	30+23	0.00	New Dorp Ln	South	Cherry	3	Good	No	0		STP
31	29+37		New Dorp Ln (On Milton Ave)	South	London Planetree	28	Poor	Yes	0	Roots girdling, slim flux	*REMOVAL
32	28+46	2.19	Finley Ave (On Milton Ave)	South	Oak	22	Excellent	No	0	Behind fence - beyond property line	STP
33	28+01	DEAD	Milton Ave	South	DEAD	16	Dead	Yes	1	Sidewalk heaved/cracked, root damage, behind fence	REMOVAL
34	27+45	1.45	Milton Ave	South	London Planetree	24	Fair	No	0		*REMOVAL
35	27+14	1.17	Milton Ave	South	London Planetree	20	Good	No	0		REMOVAL
36	26+64	0.77	Milton Ave	South	London Planetree	30	Good	No	0		REMOVAL
37	26+42	0.77	Milton Ave	South	London Planetree	30	Fair	No	0	Growing into sidewalk	REMOVAL
38	26+21	0.61	Milton Ave	South	London Planetree  London Planetree	30	Poor	No	0	Trunk damage	REMOVAL
			Beacon PI (On Milton Ave)		London Flametree					. ram aamago	NEIVIOVAL
39	25+98	NF NE	·	South		30	Not Found	No	0		
40	25+77	NF	Beacon PI (On Milton Ave)	South	Collon, Door	47	Not Found	No	0	Prick planter	OTD
41	24+72		Beacon PI (On Milton Ave)	South	Callery Pear	9	Good	No	0	Brick planter	STP
42	24+41	-0.24	Beacon PI (On Milton Ave)	South	Callery Pear	9	Good	No	0	Brick planter	STP
43	23+00	0.46	Milton Ave	South	London Planetree	18	Fair	No	0	Girdling roots; root damage, leaning trunk	REMOVAL
44	22+72	0.73	Milton Ave	South	London Planetree	36	Poor	Yes	0	Growing into road, curb damage, leaning trunk	*REMOVAL
45	21+29	0.54	Milton Ave	South	London Planetree	30	Good	Yes	0	Growing into road, curb damage, unbalance crown	REMOVAL
46	21+05		Milton Ave	South	STUMP	24	Poor	No	0	Growing into road, unbalance crown	REMOVAL
46A	20+20		Milton Ave	South	Cherry	2	Excellent	No	0	Newly planted	REMOVAL
47	19+35	0.47	Milton Ave	South	London Planetree	28	Poor	No	0		REMOVAL
GEND:		Tree marked by N	YCDPR for removal - no restitution	1		**REMOVAL = R	emoval without res	<u> </u>	1	STP = Standard Tree Protection	MTP = MultiTree Protecti

NO. DATE DESCRIPTIONS BY APPR'D CITY OF NEW YORK FINAL DESIGN PREPARED BY: TOPOGRAPHIC SURVEY PREPARED BY: TREE IMPACT MITIGATION TABLES ROMA AND HETT AVENUES DEPARTMENT OF DESIGN AND CONSTRUCTION DRAWN BY \_AJC STV Incorporated SCALE: BOROUGH OF STATEN ISLAND B. THAYER ASSOCIATES DIVISION OF INFRASTRUCTURE CADD FILE \_\_TT01.dwg AS SHOWN LICENSED LAND SURVEYOR SIGNATURE OF PRINCIPAL DATE **BUREAU OF DESIGN** CAPITAL PROJECT NO. HWR669C SHEET 123 OF 159 TT08